

US Army Corps of Engineers

Construction Engineering Research Laboratory

USACERL TECHNICAL REPORT P-90/16
June 1990

# AD-A225 884

# Preventive Maintenance Program: Evaluation and Recommendations for Improvements

by Donald K. Hicks

This report evaluates the Army Preventive Maintenance (PM) Program for buildings and structures, and utilities, discusses problems with the program, and recommends solutions. The evaluation describes preventive maintenance documentation and operating procedures, including the Self-Help (SH) Program for family and troop housing, analyzes the existing variations in performance of preventive maintenance, and looks at the quality of the existing preventive maintenance data and recordkeeping information as it is kept in the Integrated Facilities System (IFS) records.

The data obtained show that significant improvements could be made to the program and to the recordkeeping that would result in significant cost reductions to real property maintenance and repair costs. Based on the results of the analysis, recommendations are given for improving the existing preventive maintenance methods and procedures in resource management and decision support.



The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official indorsement or approval of the use of such commercial products. The findings of this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

DESTROY THIS REPORT WHEN IT IS NO LONGER NEEDED

DO NOT RETURN IT TO THE ORIGINATOR

# REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-0188

Public reporting burden for the collection of information is estimated to average 1 neur per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Hewiquarters Services, Directorate for information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0138), Washington, DC 20503.

1. AGENCY USE ON. ' (Leave Blank)	2. REPORT DATE June 1990	3 REPORT TYPE AND DATES COVE Final	RED
4. TITLE AND SUBTITLE	Julic 1990	Fillat	Ts. FUNDING NUMBERS
Preventive Maintenance Pr	moram: Evaluation and Re	ecommendations for	5. FUNDING HOMBERG
Improvements	06144411 M1444411011 4112 1 1 1	AAAIIIIIAIAIAAAAAAAAAAAA	* 1 0 T0700000
Improvements		!	IAO-E87880261
6. AUTHOR(S)			(dated September
o. Author(s)			1988)
Danild IZ III alaa			
Donald K. Hicks			
7. PERFORMING ORGANIZATION NAME(S	S) AND ADDRESS(ES)	<del></del>	8. PERFORMING ORGANIZATION
7. FEMPORISMA CHARICATION MAINLY	·		REPORT NUMBER
U.S. Army Construction E	ingineering Research Labor	ratory (USACERL)	
P.O. Box 4005			TR P-90/16
Champaign, IL 61824-400	05		
Consistent windshift principle	•		
9. SPONSORING/MONITORING AGENCY I	NAME(S) AND ADDRESS(ES)	`,	10. SPONSORING/MONITORING
YIO A TELOO		•	AGENCY REPORT NUMBER
USAEHSC			
ATTN: CEHSC-FB-S			
Ft. Belvoir, VA 22060-55	116		1
* - * ***	and the second s		
11, SUPPLEMENTARY NOTES			
Copies are available from	the National Technical Inf	formation Service, 5285 Por	t Royal Road,
Springfield, VA 22161		•	
12a. DISTRIBUTION AVAILABILITY STATE	MENT		12b. DISTRIBUTION CODE
Approved for public release	as distribution is unlimited	1	
Approved for public releas	se, distribution is diminificed	1.	
13, ABSTRACT (Maximum 200 words)			<del></del>
V.			
This report evaluates the Arm			
utilities, discusses problems v			
ventive maintenance documer	ntation and operating proce	edures, including the Self-H	lelp (\$14) Program for
family and troop housing, and			
looks at the quality of the exi	isting preventive maintenar	nce data and recordkeeping	information as it is kept
in the Integrated Facilities Sy	stem (IES) records.		` -
			•
The data obtained show that	significant improvements (	could be made to the progra	im and to the record
keeping that would result in s			
Based on the results of the ar			
maintenance methods and pro	ocedures in resource manage	gement and decision suppor	+ //
manus medicas and pre	roodatos in rosoarce manag	sement and decision suppor	"BUYWORDS.
			X
14. SUBJECT TERMS	ua auna - 4		15. NUMBER OF PAGES
Preventive Maintenance-Pr	ogram	1.1)/	39
preventive maintenance	Army Personnel.	(CP)	16. PRICE CODE
17 SECURITY CLASSIFICATION	Can oppulation and a second a second	<u> </u>	
OF REPORT	18. SECURITY CLASSIFICATION OF THIS PAGE	19. SECURITY CLASSIFICATION OF ABSTRACT	20. LIMITATION OF ABSTRACT
Unclassified	Unclassified	Unclassified	SAR
	<u></u>	L	~

# **FOREWORD**

This research was conducted for the U.S. Army Engineering and Housing Support Center (USACEHSC), under Intra Army Order Number E87880261 dated September 1988, "Integrated DEH Preventive Maintenance System." The Technical Monitor was Mr. Michael Smith, CEHSC-FE-B.

The work was performed by the Facility Systems Division (FS), U.S. Army Construction Engineering Research Laboratory (USACERL). Dr. Michael J. O'Connor is the Chief of USACERL-FS.

LTC E.J. Grabert, Jr. is Commander of USACERL, and Dr. L.R. Shaffer is Director.

Access	ion For	
NTIS	GRA&I	
DTIC T		밀
Unanno		
Justii	ication	
Avai	lbution/ lability Avail a	Codes
Dist	Speci	
By		



# **CONTENTS**

		Page
	SF 298 FOREWORD LIST OF TABLES AND FIGURES	1 2 4
1	INTRODUCTION	5
2	DATA COLLECTION AND ANALYSIS  Data Collection Quality of IFS Data Results of Data Analysis	7
3	PREVENTIVE MAINTENANCE PROGRAM Program Overview Requirements Program Execution	13
4	ANALYSIS OF PREVENTIVE MAINTENANCE PROGRAM  Introduction General Observations Organization Operations Management Recordkeeping Training	18
5	CONCLUSIONS AND RECOMMENDATIONS	30
	ABBREVIATIONS	32
	APPENDIX A: Standard PM Task List for Doors APPENDIX B: High Frequency Task List APPENDIX C: High Costs Task List	33 35 36
	DISTRIBUTION	

# **TABLES**

Num	ber	Page
1	Relative Physical Size Comparison	18
2	Installation's Army Mission	19
3	Total Costs for Maintenance and Repair	19
4	Total Preventive Maintenance Costs	20
5	Cost of PM Program Executing Self-Help	. 21
6	Housing Maintenance and Repair Costs	21
7	Unit M&R Costs	22
8	Preventive Maintenance Task Codes	25
9	Fort Bliss High-Frequency Tasks .	25
10	Fort Devens High-Frequency Tasks	26
11	Fort Devens High-Duration Tasks	27
12	Fort Eustis High-Frequency Tasks	27
13	Fort Eustis High-Duration Tasks	27
	FIGURES	
1	Maintenance and Repair of Real Property Cost Trends	14
2	Army Family Housing Maintenance Trends	15
3	Labor Costs for Utilities	23
4	Labor Costs for Buildings and Structures	24

# PREVENTIVE MAINTENANCE PROGRAM: EVALUATION AND RECOMMENDATIONS FOR IMPROVEMENTS

#### 1 INTRODUCTION

#### Background

Performing preventive maintenance (PM) to reduce maintenance cost and interruptions caused by breakdown has been an integral part of the Army Maintenance System for many years. Preventive maintenance is a cost-saving, sensible practice now accepted by most industries. Many case studies could be developed to demonstrate the derived benefits and the impact on Army readiness. Over the years changes have been made in the program both to reflect the current needs of the Army and to accommodate changes in attitude and leadership. In view of the high cost of PM operations, however, the question is whether the Army is making good use of the program. The Army may be paying more for PM than it would cost periodically to replace broken equipment. Breakdown maintenance on many components and equipment may be inexpensive and not impact operations, thus eliminating the need for PM on these components. Is the Army making the best use of its maintenance resources?

Preventive Maintenance is divided into two broad categories: (1) Buildings and Structures and (2) Utilities. This report covers both categories. Within each category are four groups of task types (work codes): inspection, minor repair and service, reporting to the appropriate shop needed repairs that are beyond the scope of work for the PM team, and nonproductive, administrative, and travel/break codes. Part of the Preventive Maintenance Program is the Self-Help (SH) Program, in which the occupants of family and troop housing perform limited maintenance and repair work and minor improvements to their quarters.

# **Objective**

The objective of this report is to analyze the existing Preventive Maintenance Program composition, recommend improvements to existing methods and procedures, and identify areas for further study, test, and evaluation.

#### Approach

A multiphased approach was used to provide in-depth analysis of the PM Program. Installation Directorate of Engineering and Housing (DEH) personnel, civilian property and Preventive Maintenance Program managers, and family housing (FH) Self-Help Program administrators were surveyed by site visits and telephone inquiries to obtain direct user input about the current program. Department of the Army (DA), Department of Defense (DOD), and Major Command (MACOM) documentation providing PM guidance, as well as previous research, was evaluated. Recommendations were made for improving the program based on the data analysis, DEH personnel responses, and commercial practices.

# Scope

This report covers the first phase of a multiyear study to evaluate the program, to redefine its operations if necessary, to provide guidance on eliminating tasks that should not be included in the program, and to integrate the work with the Maintenance Management System (MMS) and other computer programs designed to assist maintenance managers.

# Mode of Technology Transfer

Results of the study will be transferred to DEH organizations through documents, onsite technical assistance, and revision of Army Regulation 420-22, *Preventive Maintenance and Solf-Help Programs* (HQDA, 6 July 1976) and supporting technical manuals (TMs).

#### 2 DATA COLLECTION AND ANALYSIS

Evaluation of the PM program and recommendations for program change were based on intensive data collection. Information was gathered by (1) telephone interviews with PM personnel at 13 continental United States (CONUS) installations, (2) in-depth site visits to three installations, (3) telephone interviews with civilian property managers, (4) examination of Integrated Facilities System (IFS) records from 9 installations, and (5) review of previously published research. The information obtained was used to establish a baseline for comparison and evaluation.

#### **Data Collection**

#### Telephone Interviews with Installation Personnel

Telephone interviews with PM personnel at 13 CONUS installations were used to obtain baseline data and to help determine which installations would be visited for in-depth evaluations. Most often interviewed were the Public Works Directorate (PWD) chiefs, PM shop foremen, SH coordinators and service center managers, family housing (FH) representatives, and budget analysis personnel. Directorate of Engineering and Housing (DEH) office representatives provided information about the overall program, including the interaction between PM and SH, the general attitude toward PM's inclusion of SH, the mechanics of the PM Program including the SH aspects, and cost-reporting/accounting procedures. Discussions were also conducted with the Management Engineering Services (MES) branch of the DEH about the Maintenance Management System (MMS) and the Integrated Facilities System (IFS). PM foremen were interviewed to obtain information about (1) overlaps between the PM and SH programs, (2) policy directing PM team members' efforts and responsibilities regarding FH, and (3) the incidence of the need to rework incorrectly completed SH tasks. SH service center managers and foremen provided detailed information about daily SH operations.

#### Site Visits

Three sites were chosen. Many factors were considered during the selection process, including physical size, geographical locations, major command (MACOM) affiliation, PM management style and philosophy, high ratings (by their respective MACOMs) of PM Programs, and the completeness of the IFS recorded data.

During each site visit, personnel associated with the following DEH activities were interviewed: PM, FH, SH, budgeting, supply, MES, and repair and maintenance. At installations using Commercial Activities (CA) contracts, personnel doing quality assurance evaluation of the contracted maintenance were interviewed. The site visits provided a significant amount of detailed information. They also gave researchers firsthand impressions and subjective evaluations that contributed to understanding of the less quantifiable issues underlying implementation of a successful program.

# Telephone Interviews with Civilian PM Managers

Telephone interviews were conducted with maintenance managers of several major industrial and commercial corporations and a large university regarding their approach to preventive maintenance. The conversations were enlightening about how nonmilitary organizations conduct preventive maintenance programs. Discussions and telephone interviews were conducted with a large public university, a

multinational coatings and adhesive manufacturer, an international fast-food franchiser, and a U.S. automobile manufacturer.

# IFS Record Analysis

iFS records stored on machine readable data tapes were acquired from nine U.S. Army installations. IFS records for FY85 and FY86 were reviewed for all installations. Based on the relative completeness of IFS data, site visits, geographical location, and telephone conversations with DEH personnel, three sites were chosen for further study and analysis of their PM efforts. FY86 IFS data for Fort Eustis, Fort Devens, and Fort Bliss were selected.

#### Previous USACERL Research

Previous research<sup>1</sup> conducted and published by USACERL into the PM and SH function of the DEH was reviewed, and investigators were consulted. The results of these consultations were incorporated into this report as appropriate.

#### Quality of IFS Data

As explained below, IFS system data are not considered highly accurate, and analysis and findings based on such data reflect its inaccuracy. In contrast, this report focuses on general rather than specific aspects of PM. IFS data appear to be sufficiently accurate to define patterns and trends and, thus, will be used for that purpose.

The data recorded in IFS were investigated and found not to represent work performed. PM team operations were observed in the field at several installations. Workers reported enough tasks to justify their workdays and distributed their time accordingly. In addition, workers performed several more tasks each day than the number reported. In the workers' opinion, because no one used the time-per-task figures, concern about their accuracy was unnecessary. They saw confirming that they had worked a fulday as the only significant item to report. If this is common practice, the reported labor hours are overstated.

Some installations, however, manage their crews dynamically using radio communication. Task performance is compared with the Engineered Performance Standards (EPS)\*. If the lapsed time exceeds the EPS, a dispatcher asks workers to explain the delay. The dispatcher assigns new tasks once workers have completed other tasks. Data from these installations may be more accurate but workers may perform small tasks not recorded in a normal workday. On other installations, workers are thought to stretch the time per task to fill the day, with resulting low productivity. Given this variety of conditions, the present assessment is based on the assumption that the reported data is accurate and appropriate enough to serve as the basis for recommending program changes.

<sup>&</sup>lt;sup>1</sup>J.H. Williamson, A.E. DeLong, C.J. Norris, and S.E. Glaeser, Family Housing Self-Help Program: Evaluation and Recommendations for Improvements, Technical Report P-86/08 ADA171466 (U.S. Army Construction Engineering Research Laboratory, July 1986).

TB 420 Series.

#### Results of Data Analysis

Telephone Interviews and Site Visits

<u>Preventive Maintenance</u>. The PM program is in place and working to some degree at all the installations surveyed. The degree of involvement seems to depend on the availability of personnel and funds for PM. Because PM is part of the more inclusive Real Property Maintenance Activity (RPMA) program, some installations have shifted their PM focus from inspection to repairs. This approach reduces the probability that the program is working as intended, that is, eliminating repairs through PM inspection and maintenance. This action also represents a significant philosophical change regarding PM.

<u>Self-Help.</u> SH programs are used primarily in family housing, although some SH projects are done in troop housing and other buildings. SH is expanding to include various improvement programs such as "U-DO-IT," for small remodeling and addition projects. The degree of complexity varies with labor skills and installation funds available for such projects.

<u>Management</u>. Management of PM varies from installation to installation according to management styles, installation organization, and other poorly defined criteria. Some factors influencing management are administrative attitudes on relative value of PM, budget considerations and constraints, the impact of CA studies, staffing levels, and previous experiences in PM program management.

Organization. The organization of PM varied from installation to installation and, in some cases, from year to year on the same installation. In most cases, however, PM fell into one of the following categories:

- Conventional: The PM mechanic or team inspects a facility, makes minor repairs, and reports larger repair requirements for service order repair action.
- Spot fires: Very little PM is accomplished; the mechanics primarily respond to emergency calls, which occupy most available time.
- Iceman: PM mechanics cruise areas of family housing. If occupants need PM services, they display a card in the front window. The PM mechanic contacts the occupant and arranges for the PM work.
- Radio controlled: PM mechanics are directed to each call by a dispatcher using a two-way radio system; PM mechanics are directed to emergencies as they arise.
  - Other: These are combinations of the above categories.

<u>Budget</u>. The budget for PM is perceived vulnerable to funding cuts because it lacks demonstrable benefit. In addition, PM program managers are unable to show hard data on the results of the PM effort to the budget administrators because data do not exist or are not in usable form.

<u>Support.</u> Most DEH and PM program managers agree that PM is cost-effective and needs to be expanded to have demonstrable benefit. Being able to demonstrate clearly positive results of PM will contribute significantly to informing those who make decisions concerning the PM Program.

Training. The Army hires people for PM work who have considerable maintmance and repair experience. No formal training program exists for newly hired mechanics. Less experienced mechanics learn specific shop procedures and techniques from senior mechanics. Interviewees indicated that formal training would be beneficial for PM mechanics servicing buildings, structures, and utilities.

Supervisors and mechanics indicated, moreover, that most PM documentation is outdated and nonspecific. For example, the current PM manual for kitchen equipment, TM 5-637, was published in July 1945. The expressed need was for revised technical manuals with specific guidance for conducting inspections and other PM tasks (e.g., "calibrate the thermostat" rather than vague statements like "check thermostat"). The consensus was that improved manuals would upgrade the effectiveness of PM.

# The Civilian Approach to Preventive Maintenance

Maintenance personnel at private institutions/industries were interviewed by telephone. They provided information on preventive maintenance programs at the corporate and/or local level. PM practice varied widely among these firms.

Auto Manufacturer. The auto manufacturing company had two extremes of PM. At the corporate headquarters PM was not practiced; instead, breakdown maintenance was relied upon. The decision to use the breakdown approach was based on an estimated lack of return on the investment (ROI) needed to maintain a formal PM program and a belief that maintenance problems would not cause a loss in staff productivity. However, at the company's manufacturing and assembly plants, formal PM programs using computer-generated PM work schedules were in place.

The initial framework for the computer-based data management system was developed by the corporation. Local maintenance personnel added information about buildings and equipment, type and amount of PM required, and task performance frequencies. The computer generates a maintenance card daily for each mechanic detailing the day's tasks. After the mechanic completes all tasks and so notes on the card, he returns it and this data is recorded in the program. Unfinished tasks are listed on the next day's card of tasks, which ensures that specific tasks do not appear more than once during a cycle. Individual PM systems constitute a network that allows information sharing between local installations. Thus, if one installation sets up a program for a given piece of equipment, another installation can input the information into its system. This design was in place at an automobile assembly plant, where a breakdown or interruption of service would have resulted in substantial productivity loss.

Fast-Food Franchiser. At the surveyed fast-food restaurant company, corporate-level personnel developed the PM schedule listing task description and required PM frequencies for each piece of equipment for local restaurants. The program is described in detail in various manuals provided to restaurant managers. Buildings and equipment were usually set up on 6-month PM cycles. Restaurant managers set up an annual calendar for completion of tasks. Maintenance personnel work from a daily PM task list. Preventive maintenance is performed according to detailed guidance given in the equipment manuals. Most of these PM inspections are performance related, if the item does not meet specified performance levels, equipment repair and adjustments are made. This type of PM program is very efficient because buildings and equipment are standardized and the corporation exercises considerable control. As in the case of the auto assembly plant, a breakdown would result in lost production and revenue, and possibly a loss of reputation.

Adhesive Manufacturer. The international coatings and adhesive manufacturer is setting up a company wide PM program. Currently, each plant operates its own minimal PM. These programs are based on insurance carrier requirements and consist of inspecting fixed fire equipment, overhauling major electrical systems every 3 years, and inspecting the roofs every 5 years. Most of the work is performed by contractors specializing in PM. The contractor establishes and proposes a schedule for PM work, the corporation reviews and approves the schedule and makes periodic quality assurance inspections. A PM scheduling program now being developed will be computer-generated and more inclusive than those currently in use.

Public University. The university in the survey practices extensive PM, which is accomplished using teams organized by task types. For example, a team of mechanics walks the underground utility tunnels daily looking for breakdowns and potential problems, such as leaking water or steam pipes. Building inspections are conducted on 3- to 5-year intervals with teams consisting of a general inspector, a mechanical inspector, and an electrical inspector. The team has the authority to request up to \$2,500 worth of immediate repairs to alleviate a hazardous or potentially dangerous situation. Inspection teams also report housekeeping problems, relating primarily to health and safety, to the various department heads, who are responsible for correcting the problems. Roofs are inspected, and records of the moisture content of the roofs are kept to determine if the roofing system has deteriorated since the last inspection. Based on this data, appropriate repair/replace actions are taken. Air-conditioning and air-handling filters are checked periodically. Cooling towers are serviced in the fall for shutdown and winterization and in the spring for start-up. Building cevators are serviced and cables lubricated. Adjustments to elevator doors are made twice a year and are ... heduled in advance of official building inspections. General illumination lamps are changed en masse after 10 to 15 percent of the lamps have failed in an area. A vibration team checks reported building vib. ations, identifies the source of the vibration (usually in the mechanical equipment) and makes appropriate repairs.

The manufacturing/assembly PM program is closely related in structure to the Maintenance Management System (MMS) that is installed (or scheduled to be installed) and is currently being tested at Fort Ord, CA, Fort Jackson, SC, 1 · McCoy, WI, and Fort Eustis, VA. The primary difference between the two systems is that the MMS does not have the capability to share information with other installations. Adding this capability to the MMS would be beneficial, especially for installations placing new equipment in the PM program. If one installation already has this equipment type in its PM program, the installation just acquiring it could benefit from the first installation's experience in setting up its own PM tasks.

# Integrated Facilities System (IFS) Record

The IFS data for three sites for FY86 were analyzed to determine the following information:

- 1. Total monthly and annual cost of PM performed by DEH mechanics according to civilian and military labor costs, shop stock supply and nonshop supply costs, equipment rental and depreciation costs, and other costs.
- 2. Total monthly frequency of PM tasks according to equipment type, installation number, and building/facility number.
- 3. Frequency of PM tasks versus frequency of repair according to date, total cost, equipment type, installation number, and building number.

- 4. Total monthly and annual cost of PM for all family housing units.
- 5. Monthly frequency of PM in family housing, broken down by task, labor cost, material (supply) cost, and equipment cost (rental and/or depreciation).
- 6. Average cost and labor hours associated with each PM task (because each installation is allowed to define its own task codes independently, these averages will have to be developed for every PM task defined by each installation).
- 7. Labor hours and cost of tasks performed by the PM shop personnel which the occupants could have performed (i.e., self-help tasks).

This information was correlated, charted, and analyzed to determine the status of PM at the selected sites.

During the data collection period a number of the selected installations were in some phase of the commercial activities (CA) review process. IFS information was not available from these installations due to the sensitivity of the data in the CA process. Also, contacts indicated that CA studies influenced how mechanics and supervisors recorded labor and equipment data for PM activities. It was found that at installations under CA review, workers made an effort to record performance data more accurately.

The level of detail recorded in IFS data at some installations was inadequate for CA studies. As a result, IFS was either altered or abandoned at those sites. At Fort Eustis and Fort Bragg a more thorough analysis of ongoing work was needed for CA studies. Originally, a two-character numeric code was used for coding tasks. This system limited the user to 100 task descriptions. Fort Eustis changed to a two-character alphanumeric code. Now more task descriptions are available for each shop. The analysis used in this report is based on the expanded coding system.

Fort Bragg also modified the IFS to make it more useful. IFS will allow only three task codes to be entered under a single service order; more than three will result in an error message. By increasing the number of task codes per service order, Fort Bragg would generate a more accurate analysis for the purpose of CA studies. dBASE III is used to generate work order history files. Their IFS data is complete except for task codes which are recorded separately in the dBASE files.

Also, some changes in maintenance work procedures have resulted from CA studies. Concern about losing their jobs to commercial contractors has made foremen and workers more efficiency-oriented. They frequently change work methods, scheduling, and other aspects of their work to improve productivity. If one looks at IFS data for a given year, what appear to be peaks or lulls in frequencies, costs, or labor hours may actually reflect operational changes. In some cases, work force size has diminished due to CA studies. PM personnel openings often are not filled to reduce operating cost and be more competitive with commercial contractors.

#### 3 PREVENTIVE MAINTENANCE PROGRAM

#### **Program Overview**

The PM and SH programs are mandated by Army Regulation (AR) 420-22<sup>2</sup> and are defined as follows:

Preventive maintenance is the systematic care, servicing, and inspection of equipment, utility plants and systems, buildings and structures, and ground facilities for the purpose of detecting and correcting incipient failures and accomplishing minor maintenance. . .

The Self-Help Program involves military personnel and occupants of family/troop housing in accomplishing limited maintenance and repair work and minor improvements in family housing. . .

Installation commanders are responsible for the programming and accomplishment of the preventive maintenance program and for establishing and administering the self-help program at installations under their jurisdiction. . .

The facilities engineer is responsible for providing technical guidance and assistance to participants in these programs. . .

As shown in Figures 1 and 2, the costs of maintaining family housing and all real property have risen dramatically in recent years. Because maintenance costs include PM costs, and because PM costs have risen correspondingly, a significant effort toward making overall PM more efficient and cost-effective is necessary.

#### Requirements

#### Description of Current Documentation


Guidance documentation and regulations for the PM Program are defined in the Technical Manual (TM) 5-600 series and supplemented by DA³ and MACOM⁴ publications. Occupant guidance for the Self-Help Program is provided in the same DA pamphlet and in technical bulletins.⁵

Preventive maintenance requirements for buildings and structures as detailed in the TM 5-600 series, consists of inspecting building component conditions and preparing work orders. Timing and phasing are not considered in the inspection task list for buildings and structures, which is enumerated in

<sup>&</sup>lt;sup>2</sup>AR 420-22, Preventive Maintenance and Self-Help Programs (HQDA, 6 July 1976).

<sup>&</sup>lt;sup>3</sup>DA Pamphlet 210-1, Handbook for Family Housing Occupants (HQDA, 15 September 1971).

<sup>&</sup>lt;sup>4</sup>TRADOC Regulation 420-5, *Preventive Maintenance and Self-Help* (U.S. Army Training and Doctrine Command, 11 June 1982). <sup>5</sup>Technical Bulletin ENG 402, *Facilities Engineering Self-Help Program* (HQDA, 16 July 1970).




During this 10—year period maintenance and repair of real property costs increased by \$1,215 million or 154.4 percent (\$2,002 vs. \$787 million).

The average increase was \$122 million or 15.4 percent per annum.

The largest increase took place in Fiscal Year 1982 — \$144 million or 36.6 percent above Fiscal Year 1981 (\$1,645 vs. \$1,204 million).

• In Fiscal Year 1986 maintenance and repair of real property costs increased by \$107 million or 5.6 percent above Fiscal Year 1985 (\$2,002 vs. \$1,895 million).

Figure 1. Maintenance and repair of real property cost trends.



Army Family Housing — Maintenance rose from \$300 to \$526 million from Fiscal Years 1981 through 1986 — an increase by \$226 million or 75.3 percent.

Annual increases from Fiscal Years 1982 through 1985 were as follows:
\$8 million or 3 percent in Fiscal Year 1982.
\$11 million or 36 percent in Fiscal Year 1983.
\$74 million or 18 percent in Fiscal Year 1984.
\$79 million or 16 percent in Fiscal Year 1985.

Maintenance decreased by \$46 million or 8 percent In Fiscal Year 1986 Family Housing — below Fiscal Year 1985.

Figure 2. Army family housing maintenance trends.

TM 5-610.6 The utilities task list (see, for example, TM 5-6377) emphasizes performing tasks to improve equipment operations, including changing filters, making minor adjustments/replacements, and inspecting for major repairs.

Each installation defines PM according to its perceived requirements, its managers' personalities, and local tradition. To illustrate the varying perceptions of which tasks are to be performed, Appendix A lists the standard PM task codes and task descriptions for the surveyed installation for door PM.

In general, PM for buildings and structures has changed from being primarily inspection to performing minor repair. Organization of shops and crews varies widely, but always includes a team specializing in performing preventive maintenance on buildings and structures. Skills represented on the team indicate management's emphasis in this area.

#### Evaluation of Current Documentation

The TM 5-600 series of technical manuals for the PM Program is antiquated and inadequate for today's requirements. Some of this information dates back to the mid-1940s and discusses equipment and procedures of that era. Given technological advancements of the past 40 to 50 years, far better guidance and documentation can be provided. For example, PM mechanics now rely primarily on service recommendations provided by the equipment manufacturers. Because building equipment is not standard in an installation, mechanics maintain several makes and models of each equipment item and must be familiar with their service requirements. This lack of standardization is the result of using competitive contracts, and the practice complicates maintenance activities.

# **Program Execution**

#### Fort Bliss

The PM shop staff consists of 23 mechanics (two master plumbers), four locksmiths (two temporary), and one shop supervisor. The master plumbers' salary grade is higher than that of the other PM shop mechanics. A team of PM mechanics spends the first half of the week working in troop housing and the rest of the week inspecting and repairing recently vacated family housing units with the rest of the mechanics. No cyclic PM is performed for family housing; repair and maintenance services must be requested from the work order desk. Cyclic PM occurs only in troop housing and post buildings.

PM operations in a typical utility shop are similar to those of the refrigeration shop, which has one foreman, three leaders, one clerk, three emergency mechanics, and 15 specialized mechanics. Each mechanic is assigned a geographic area of the post. In the morning a mechanic inspects part of the facilities in that area. (This is not a PM inspection, but rather a search for repairs.) The mechanic returns in the afternoon to make the repairs. The day ends with another inspection of the same facilities to determine if all the work was completed; if not, it is rescheduled for the following day.

This shop is working with less than half the staff it had 10 years ago. Nevertheless, by using the inspection systems, the mechanics identify and correct problems before breakdown failures occur, thus reducing total operational costs and saving time. Despite the efficiency of the inspection systems, however, labor shortages persist and much of the work is contracted out. For example, all filter

<sup>&</sup>lt;sup>6</sup>TM 5-610, Preventive Maintenance: Facilities Engineering, Buildings and Structures (HQDA, 1 November 1979).

<sup>&</sup>lt;sup>3</sup>TM 5-637, Inspection and Preventive Maintenance Services for Kitchen Equipment (HQDA, 25 July 1945).

replacement and over 70 percent of maintenance on evaporative coolers are contracted out. One mechanic is responsible for the performance and quality inspection of all work done by contractors.

#### Fort Devens

Cyclic PM is done on both administrative and billeting cantonement (i.e., winterized and occupied year-round) structures. The facilities PM force is made up of 17 men: 14 PM mechanics, two working leaders (one for FH/TH and one for administration buildings), and the PM shop supervisor. The force is divided into 10 teams. Four one-person teams work in FH, and each is permanently assigned to a certain area. Family housing PM work is performed when a displayed PM card is seen, by appointment, or by service order. Four teams perform PM on administrative and billeting facilities. Two one-person teams work on administrative buildings and two two-person teams work on barracks. Each of these four teams works in an assigned area and completes a PM cycle every 16 weeks.

Fort Devens has six utility shops, and most utilities PM is done annually. Boilers and heat plants are inspected and maintained in the summer, and air-conditioning and refrigeration units are primed in the winter. The water distribution system is checked and maintained throughout the year as needed (e.g., the valves are exercised twice a year). A line crew continuously maintains the electrical distribution system. The utilities PM work is funded via long-phased individual job orders (IJOs), and each year an IJO is issued for PM specific to a certain type of equipment. For example, an IJO is issued at the beginning of the fiscal year to inspect and maintain all boilers, and the work is completed throughout the year.

#### Fort Eustis

The PM shop, along with eight other shops, is responsible for the performance of PM for buildings and related utilities. The tasks of the PM mechanics are limited in size and skill level and are usually performed in family housing (FH), troop housing (TH), and post buildings.

The PM shop staff has been reduced from 22, an all-time high 12 years ago, to its current size of 9 mechanics. PM shop mechanics cover an assigned area of the post. The two two-person post buildings teams split the more than 500 permanent, semipermanent, and temporary buildings between them. One team covers the northern half of the installation, and the other, the southern half. The four FH teams cover a roughly equal amount of the 1335 FH units. The two-person FH team (the others are single-person teams) is assigned to the older units, which require more maintenance.

Cyclic maintenance is scheduled for post buildings and FH units. Post buildings are on a 180-day cycle, FH units are on a 120-day cycle. Each week a list of the buildings and FH units scheduled for PM is printed in the post bulletin. Typically, a family housing PM mechanic will begin his day by correcting deficiencies in vacant quarters the day after the occupants' household goods have been removed. (Fort Eustis requires occupants to schedule a PM visit after the quarters have been inspected by family housing personnel and before clearing.) After the mechanic has made his scheduled PM calls to inspect vacant FH units, he responds to work orders and displayed PM cards as time permits. The PM card is a displayed signal device, which is included in the FH packet given to new occupants upon arrival. These cards are placed in a street side window of a unit when a PM mechanic is scheduled to be in the area, similarly to how ice deliveries were made for ice boxes at the turn of the century. The PM card alerts the mechanic that the occupant is requesting service. The scope of the PM mechanic's work is covered in the FH information packet.

The remaining shops usually do not follow a schedule of cyclic maintenance. Their scope of work includes large-scale repairs. The utility shops perform PM and inspection as often and as regularly as possible, but inspections usually occur when other repairs are being made, and PM is usually done during the off-season.

#### 4 ANALYSIS OF PREVENTIVE MAINTENANCE PROGRAM

#### Introduction

The analysis of the Preventive Maintenance Program data (primarily IFS data) was limited to a sample of three installations. The investigation focused on current activities to determine whether improvements could be made by either applying new technology and computer automation support or reorganizing operations. The following analysis was generated from the IFS data of the sample installations and other sources as noted; however, it is thought to be closely correlated to, and fairly representative of, PM programs of all nine installations initially interviewed.

#### **General Observations**

To evaluate the data properly it is necessary to understand the relationship among sample installations' size, location, age of facilities, function, and Army mission. Fort Bliss had the largest housing population in the sample, with 3642 spaces, guest houses, and 7 VIP quarters. Fort Devens has a smaller population, with 1723 spaces, mobile home parks, and 7 VIP quarters. Fort Eustis is smallest with 1371 spaces, mobile home parks, and 7 VIP quarters. A breakdown of the statistics is given in Table 1.

Table 1\*

Relative Physical Size Comparison

		Fort Bliss	Fort Devens	Fort Eustis
Location		ТX	MA	VA
Population	Active Duty	21426	5911	8625
	Dependents	9136**	7368	na
Housing	Officers	512	323	361
	NCOs	2458	406	370
	BOQ	606	994	608
	VIP Quarters	7	1	7
	Other	66	30	32

<sup>\*</sup>Adapted from Guide to Military Installations in the U.S. (HQDA, 7 April 1986).

<sup>\*\*</sup>Off-base housing = 14,354.

Although housing capacities do not absolutely determine relative size, they are fairly accurate. Also notable is the geographical and climatic variation of the three sample installations: one Northeast, one Mid-Atlantic, and one Southwest. Fort Bliss and Fort Eustis are Training and Doctrine Command (TRADOC) installations, and Fort Devens is a Forces Command (FORSCOM) installation (see Table 2).

Table 3 compares total FY86 maintenance and repair (M&R) costs with PM costs for each installation. The total cost figures include labor, material, and equipment rental/depreciation for the shops that conduct the maintenance and repair activities.

Table 2
Installation's Army Mission

Fort Bliss, TX	TRADOC Installation: Army Air Defense Artillery, Center and School; Army Sergeants Major Academy; 3rd Armored Cavalry Regiment; German Air Force Training Command and Air Defense School; NATO Nike Training Center; School Bde.; 70th Ord. Bn.
Fort Devens, MA	FORSCOM Installation: Army Intelligence School; 10th Special Forces Group (Airborne); 39th Engineer Bn. (Combat); 36th Medical Bn.; Combat Sup. Bn.
Fort Eustis, VA	TRADOC Installation: Army Transportation School; 7th Trans. Group; Training Support Center; Applied Technology Lab.; Army Aviation Logistics School

<sup>\*</sup>Adapted from Guide to Military Installations in the U.S. (HQDA, 7 April 1986).

Table 3

Total Costs for Maintenance and Repair

	Total M&R (in millions of dollars)	Total PM (in millions of dollars)	% PM	
Fort Bliss Fort Devens Fort Eustis	27.155 17.356 16.034	0.740 1.004 1.573	2.7 5.8 9.8	

The total cost includes all PM and M&R for buildings, structures, FH, TH, and utilities. Resources invested in PM varied widely among installations for several reasons:

- condition/age of facilities,
- scope of work accomplished under PM,
- contribution to the SH, and
- extent of renovation under way at the installation.

This study does not attempt to reconcile the differences in PM investment or to validate the reported costs independently. The largest portion of PM costs is labor: Fort Bliss, 78.7 percent; Fort Devens, 63.9 percent; and Fort Eustis, 63.5 percent. The details of PM costs are given in Table 4.

#### Self-Help

Cost data analysis disclosed that a significant effort was expended accomplishing self-help tasks. These tasks are defined by USACERL as the responsibility of FH and TH occupants. The average installation PM investment in SH averaged \$117,738 per year. As a percentage of the PM budget, the SH investment varied from 3.5 to 18.9 percent. These figures are representative, and several million dollars more PM work could be accomplished each year if SH were fully implemented (see Table 5).

# Maintenance and Repair

Table 6 lists maintenance and repair costs of housing at the three sites. This information is presented to compare and to evaluate the magnitude of the program in the housing area only.

Table 4

Total Preventive Maintenance Costs

	Fort Bliss	Fort Devens	Fort Eustis
PM Shop Labor	\$581,853	\$641,374	\$999,229
PM Shop Material	109,535	281,012	449,529
PM Shop Equipment Rental	49,187	81,705	75,065
PM Shop Equipment Depreciation	51	13	688
PM total	\$739,626	\$1,004,104	\$1,572,511
	Percentage Di	stribution	
		62.0	62 F
% Labor	<i>78.7</i>	63.9	63.5
% Labor % Material	78.7 14.8	28.0	28.6

Table 5

Cost of PM Program Executing Self-Help

Labor Costs (Annual) (In U.S. dollars)	Fort Bliss	Fort Devens	Fort Eustis
Total cost of PM mechanics loing SH in FH	\$112,143	\$126,079	\$31,655
tal cost of PM mechanics ing SH in TH	\$27,838	\$31,367	\$24,134
tal cost of PM mechanics forming SH tasks	\$139,981	\$157,446	\$55,789
tal cost of PM (Table 8)	\$739,626	\$1,004,104	\$1,572,511
ercentage of labor costs ent doing SH tasks	18.9	15.7	3.5

Table 6

Housing Maintenance and Repair Costs

	Fort Bliss	Fort Devens	Fort Eustis
Family Housing (FH)	\$ 1,526,120	\$ 1,278,087	\$ 863,351
chelor Housing (TH)	5,399,299	4,299,079	3,312,622
ousing total	6,925,419	5,577,166	4,175,973
'otal (all real property)	\$27,155,645	\$17,355,695	\$16,034,448
lousing % of total	25.50	32.13	26.04

Table 7 shows the relative M&R costs per square foot of housing in FH and TH, per Family Housing Unit (FHU), and per person housed. Population figures for active duty personnel are taken from Appendix C, Table C1; housing maintenance costs are taken from Table 6. The family housing cost per square foot is, at all three sites, considerably less than the troop housing (TH) cost. However, the perspective on maintenance cost changes when the cost per active duty person is compared to the cost per square foot of housing. The percentage of variation between installations is less when comparing the cost per person housed in either family or troop facilities than it is when comparing the cost per square not of housing. Table 7 also indicates that the cost to maintain housing facilities varies significantly among the three installations.

Table 7
Unit M&R Costs

	Fort Bliss	Fort Devens	Fort Eustis
Family Housing area (sq ft)	4,806,000	2,412,000	2,043,000
Cost/sq ft	\$0.32	\$0.53	\$0.42
Cost/FHU	\$426.79	\$741.78	\$644.77
Troop Housing area (sq ft)	3,899,000	1,857,000	1,850,000
Cost/sq ft	\$1.39	\$2.32	\$1.79
Cost/person	\$302.48	\$1,026.52	\$454.66

# Organization

The cost profile on PM team operations at three installations is shown in Figures 3 and 4. The team is treated as a subset of the shop work force and is allowed to vary during the year. The overall DEH shop work force is relatively stable, but the capability of the team is allowed to vary during the year for the following reasons:

- Capability is usually low in October due to funding uncertainty;
- PM personnel (mechanics) are assigned to other shops to perform emergency and/or other M&R work based on work priority. During peak PM periods more shop labor is invested in PM team activities; and
- During the prime months for relocating military families, the PM team is expanded to meet the work load of preparing vacated housing units before new occupants move in.

#### **Operations**

Each of the surveyed installations has a distinct operations approach to PM, as the following sections describe. The information is presented only to compare data, not to evaluate a given program.

Table 8 shows quantitative differences in PM task codes among the three installations. The impact of these variations will be discussed in the following text. (Appendix B lists high-frequency tasks, and Appendix C lists high-cost tasks.)

#### Fort Bliss

The Fort Bliss PM Team work load consists of 209 tasks, of which 36 are considered high frequency, that is, performed more than 100 times during FY86. Table 9 lists tasks most frequently performed. The portion of this work performed for FH and TH cannot be determined from IFS data.

Fort Bliss has 36 high-duration task codes (longer than 1 hour to complete), or 17 percent of the total.





Figure 3. Labor costs for utilities.



#### Fort Devens

PM Task frequency at Fort Devens is very high because significantly fewer codes are used. The PM team reported 11 tasks (out of a total of 88) performed more than 1000 times during FY86. Table 10 lists the tasks most frequently performed.

The next six high-frequency tasks were resecure/rehang wood doors, replace sliding glass doors, repair flush valve/ball cock, repair aluminum combination handles, trim doors to fit, and repair door knobs. High-frequency tasks account for 22 percent of the total PM team cost.

Table 8

Preventive Maintenance Task Codes

	Fort Bliss	Fort Devens	Fort Eustis
Fotal (all PM)	209	110	294
High frequency	36	20	91
High duration	35	11	40
High cost	<b>5</b>	6	43

Table 9

Fort Bliss High-Frequency Tasks

Frequency	Description	Unit Cost	Total	
6958	Make key from sample (one side)	\$0.84	<b>\$5,</b> 853	
2623	Repair interior door and hardware	10.78	28,275	
2323	Repair cylinder lockset	14.19	32,956	
1243	Repair lavatory faucets	7.72	6,958	

<sup>\*</sup>Note that the same shop has an average lockset reglacement cost of \$18.28, or \$4.09 additional.

Table 10

Fort Devens High-Frequency Tasks

Frequency	Description	Unit Cost	Total Cost		
6224	Repair faucet leak	\$6.37	\$39,655		
5092	Patch sheetrock wall (1 sq ft)	2.04	10,379		
2383	Repair vinyl floor tile (1 sq yd)	4.33	10,319		
2247	Free sticking window	3.96	8,899		
1866	Replace/install door knobs	11.25	20,999		

Time required to accomplish tasks tended to be shorter at Fort Devens than at Fort Bliss. Eleven tasks require 1 hour or more to complete. Table 11 lists tasks taking longest to complete.

Differences in accounting and reporting procedures prevent directly comparing installations on task frequency and duration.

#### Fort Eustis

The Fort Eustis PM team work load consists of 294 tasks, of which 20 were performed more than 100 times during FY86. Total cost of high-frequency tasks was \$39,888, or 2.5 percent of the total team cost. Table 12 lists tasks most frequently performed. (Appendix D is a composite list of high-frequency tasks for the three installations.) According to this data, high-frequency tasks do not significantly impact the total cost of the preventive maintenance effort.

Also, the time to complete each task was investigated. At Fort Eustis, 89 percent of all tasks required less than 2 hours to complete; 65 percent, less than 1 hour. Table 13 lists the tasks requiring the longest time to complete.

About 28 percent, or \$191,895, of the total cost of PM at Fort Eustis is spent accomplishing tasks that should belong in the self-help program. Of this total, labor was 78.6 percent, materials costs were almost 16 percent, and the remainder was for equipment rental. Depreciation cost was insignificant. A few PM tasks are performed by other units, notably the carpentry shop.

#### Task List Analysis

Standard task lists (Appendix A) were collected from each installation to identify the tasks performed, the scope of the work, and standard times allotted to each task. The list also allows comparing the scope of PM activities at each installation. However, several problems were soon noted. The level of detail of task description varied significantly among installations, making comparison difficult. For example, Fort Bliss allots 2.5 hours to "Replace interior door and hardware," whereas Fort Eustis lists several tasks that could be included in the same job:

Replace interior door and hardware	1.5 hours
Replace swinging door	3.0 hours
Install door hinges	0.8 hours
Replace door handles/pulls	. 0.7 hours
Replace door stop (molding)	0.9 hours.

Thus, Fort Bliss charges all replacement work on interior doors and hardware to the single general purpose work item. But Fort Eustis notes a difference between interior doors and swinging doors and provides work descriptors for replacing only some of the hardware. Moreover, this breakdown could mean that a new interior door with hardware should be installed whenever more than two pieces of hardware need to be replaced. In a separate example, the installation charges the same number of hours for repairing or replacing venetian blinds. This suggests that replacing broken blinds is as economical as repairing them.

Table 11

Fort Devens High Time-Duration Tasks

Description	Hours	Total Cost		
Replace 3 by 5 ft picture window	1.52	\$29.52		
Resecure, align, and repair screen door	1.48	25.22		
Install metal door	1.38	23.58		
Replace steel sash	1.23	21.20		
Repair and resecure door	1.11	19.20		
Replace up to 3 sq ft of wood sash	1.11	19.13		

Table 12
Fort Eustis High-Frequency Tasks

Frequency	Description	Unit Cost	Total Cost	
1029	Replace lavatory faucets	\$5.60	\$5,760	
784	Re-lamp incandescent fixtures	4.21	3,299	
546	Replace storm door closers	11.01	6,011	
489	Replace cabinet catches	4,45	2,176	
400	Secure handrails	7.29	2,917	

Table 13

Fort Eustis High Time-Duration Tasks

Description	Hours	Cost		
Replace exterior door and hardware	4.45	\$69.80		
Replace water closet	3.14	54.93		
Repair wood siding (50 sq ft)	2.50	41.42		
Prepare surface for painting (£0 sq ft)	2,47	38.39		
Replace floor door closer	2.30	36.61		
Replace screening on porch	2.21	38.39		

The lists indicate that each installation performs a different combination of tasks. Although all tasks listed appear to be within the scope of activities given in the TM 5-600 series, none of the installations perform all tasks.

It was confirmed by telephone conversation that some installations do not record inspection time; instead, inspection times are included with the repair times. Available data was inadequate to determine which inspections were made and how long it took to complete the inspection tasks.

Installations handle miscellaneous and nonproductive charges in various ways. For example, one installation routinely reports time spent for travel, breaks, standby, and administrative tasks. In addition, some installations list tasks but not estimated durations.

#### Management

PM is managed differently by each of the three sample sites, and the PM philosophy of the respective administrators varies significantly. Some examples of these differences include the following:

- Redirecting the effort of the PM crews by assigning temporary or emergency maintenance and repair work.
- As a matter of policy, having PM crews inspect and repair instead of having them inspect and report for others to repair.
- Closely managing PM crews versus allowing crews to have broader responsibility for inspecting, reporting, and repairing.
  - Establishing a lenient policy concerning PM crew performance of SH tasks.
  - Providing or failing to provide strong command support.
  - Providing or failing to provide advanced technology.

These factors would not prevent compliance with the regulations, but they would affect the spirit and degree of compliance.

Installations use their PM teams in several ways. In one approach the PM teams work in the military family housing areas and respond to residences displaying a sign in the window. The worker performs all tasks within his ability and prepares work orders for other tasks. This technique has been successful and is popular with military families. However, workers schedule their own time and decide which tasks should be accomplished.

In general, the installations are doing what is required of them under AR 420-22, supplemented by MACOM guidance. However, fiscal problems restrict all aspects of the PM Program. All managers and supervisors interviewed indicated that more resources would facilitate a better PM Program.

What remains to be done is an analysis of PM Program effectiveness and efficiency. But this will be difficult to accomplish because the necessary data are either not being recorded or do not exist in a form capable of analysis. A proper analysis of the PM Program must address questions such as the following:

Do the tasks being performed affect the ability to detect and correct incipient failures?

What happens if inspection cycles are lengthened or shortened?

How do replacement costs compare with repair costs?

Is it cost-efficient not to inspect certain items, but to repair or replace them when they fail?

Is it economical to replace an entire class of items (e.g., light bulbs) instead of replacing them one at a time?

Some installation managers attempted to adjust conditions in the PM program; however, these efforts have had very inconsistent results because they were based on insufficient analysis.

As stated earlier, PM teams typically are not performing the inspections required by AR 420-22, but are performing repair and maintenance tasks, including an amount of SH work which exceeds AR 420-22 requirements. A significant cost reduction has been realized by having PM workers perform repair and maintenance instead of requiring them to perform work for other shops. As fiscal constraints limit PM operations, inspection and testing are being reduced in scope and breakdown repair is increasing.

#### Recordkeeping

Site visits were made to observe crew operations and to interview supervisors. In general, it was found that records are kept by crew members primarily to justify their working time. The time intervals recorded, however, relate minimally to time spent performing tasks. In one case, for example, a worker was observed performing six tasks during the first hour of work but reported only nine tasks for the entire day. As a result, this kind of recordkeeping cannot be used to evaluate PM operations.

#### Training

PM mechanics are well trained and competent. The mechanics hired are already skilled, and senior mechanics and other staff train them on unique aspects of Army work.

#### 5 CONCLUSIONS AND RECOMMENDATIONS

#### Conclusions

- 1. Based on a detailed analysis of preventive maintenance at several Army installations, it can be concluded that the program works fairly well. As funding levels for PM decrease, however, more work must be accomplished with fewer resources.
- 2. Typically, PM work is not given priority, and PM is delayed while workers are assigned higher priority work. Managers lack information necessary to identify the most cost-effective activities for establishing priorities. While it is recognized that some M&R activities are given priority for other than economical reasons, the relative values of competing activities can only be generally estimated.
- 3. PM teams are performing too many self-help tasks for family and troop housing occupants. This reduces the already limited resources for PM work. According to the records of one installation, the DEH could perform over \$100,000 more PM work annually if SH tasks were eliminated.
- 4. Many technical publications supporting PM are obsolete. The TM 5-600 series of technical manuals regarding inspection and preventive maintenance is inadequate for today's requirements.
- 5. Some installations have effectively reduced costs by not performing PM inspections but instead concentrating on breakdown repair and maintenance. While this practice is somewhat effective, it reduces the opportunity to identify and repair problems at an early stage.
- 6. Little uniformity in PM programs exists among installations. Differences appear in the tasks performed, priority systems, organization structures, and recordkeeping procedures. Each installation has a unique set of task codes or descriptions. Some do not perform inspections, others perform inspections but charge time to repair activities and others (not the three referenced installations) perform and charge for inspections. Miscellaneous and nonproductive time charges are handled in different ways.
- 7. Collected field data appear to be generally inaccurate, making management decisions difficult. The cmphasis has been accounting for workers' time rather than recording the work actually accomplished.
- 8. Management control of field activities varies from monitoring and directing the work to minimal control in giving most of the daily responsibilities to the workers accomplishing the tasks.

#### Recommendations

- 1. PM activities should be analyzed using return-on-investment (ROI) techniques to determine whether the task should be accomplished and the relative value of the task, and to prioritize work load. This process will also identify activities that should be eliminated in future operations. Other installations should share in the analysis and decisions made at any given installation.
- 2. Program changes indicated by the ROI analysis should be tested or evaluated before recommending their implementation throughout the Army.
- 3. Task codes or descriptions should be standardized to simplify entry of field data, better provide understanding of content, simplify recordkeeping, and facilitate operational improvements. Standardization, such as bar code reading devices, is essential before automation.

- 4. Recordkeeping and accounting procedures should be standardized to improve managers' evaluation of program effectiveness.
- 5. A system similar to the MMS should be developed to manage PM activities related to buildings and structures, including an automated data entry system. This program should handle resource scheduling, activity scheduling, data collection, analysis, and report generation and be an interactive interface to Army standard systems.
- 6. The feasibility of applying artificial intelligence technology to the Preventive Maintenance Program through the use of an expert system to the Preventive Maintenance Program should be investigated.
- 7. The manuals in the TM 5-600 series pertaining to PM activities should be reviewed and updated. Consideration should be given to the use of more active training materials such as videotapes to increase effectiveness of the media.

# **ABBREVIATIONS**

AR: Army Regulation
CA: Commercial Activities
CONUS: Continental United States
DA: Department of the Army

DEH: Directorate of Engineering and Housing

DOD: Department of Defense

EHSC: Engineering and Housing Support Center

EPS: Engineered Performance Standards (TB 420 series)

FH: Family Housing
FHU: Family Housing Unit
FORSCOM: Forces Command

IFS: Integrated Facilities System

IJO: Individual Job Order MACOM: Major Command

MES: Management Engineering System MMS: Maintenance Management System

M&R: Maintenance and Repair

PAM: Pamphlet

PM: Preventive Maintenance
PWD: Public Works Division
ROI: Return on Investment

RPMA: Real Property Maintenance Activity

SH: Self-Help

TH: Troop Housing (bachelor or unaccompanied)

TM: Technical Manual

TRADOC: Training and Doctrine Command USACE: U. S. Army Corps of Engineers

USACERL: U. S. Army Construction Engineering Research Laboratory

APPENDLX A:
STANDARD PM TASK LIST FOR DOORS\*

		Bliss	FUI	t Eustis	ror	t Devens
Door, Door Frame, Doorbell and Panic Hardware Work	Code	Time	Code	e Time	Code	e Time
Repair interior door and hardware	AA	0.5	EO	0.6		
Replace interior door and hardware	ΑB	2.5	E5	1.5		
Repair exterior door and hardware	AC	1.0				
Replace exterior door and hardware	AD	1.5	E3	3.1		
Repair exterior wood storage door			F4	1.1		
Repair door closer and door bell	ΑE	0.5				
Replace door closer and door bell	AF	1.0				
Replace aluminum combined door closer					13	0.0
Repair panic hardwarwe	AG	1.0				
Replace panic hardware	AH	2.5				*
Repair wood/aluminum threshold	AI .	0.5	•			
Replace wood/aluminum threshold	AJ	1.0			32	0.0
Replace threshold (door)			JO	1.1		
Repair interior door jamb trim	ΑK	1.0	G2	0.9		
Replace interior door jamb trim	AL	2.5				
Repair exterior door jamb trim	AM	0.8				
Replace exterior door jamb trim	AN	4.0				
Repair exterior double door jamb	AO	0.9	F5	0.7		
Replace exterior double door jamb	AP	1.0	F6	3.7		
Repair screen door/hardware 1 each	AQ	1.0	<b>I</b> 6	1.0		
Replace screen door/hardware	AR	2.0			45	0.0
Repair shower door 1 each	BC	1.0				
Repair overhead door	C1	0.8				
Repair rails for sliding door	C2	1.7	E2	0.5		
Repair closet door			68	1.4		
Replace closet door guides			Ј3	0.4		
Replace by-pass closet door			<b>E</b> 7	5.0	39	1.0
Repair by-pass closet door track		·	10	0.4		
Replace by-pass closet door track			I1	3.5		
Repair bi-fold closet door track			12	0.5		
Replace bi-fold closet door track			13	1.2		
Replace bi-folding door			E9	2.4		
Adjust bi-folding door			E8	1.0		
Adjust closet door			<b>E</b> 6	0.8		
Replace sliding glass door					31	0.0
Adjust sliding glass door						
Repair swinging door			F0	1.12		
Replace swinging door			F1	3.0		
Repair according door			F3	2.0		
esecure/realign/repair panic hardware					25	4.3
epair/resecure door					26	0.0

<sup>\*</sup>Appendix compiled from IFS data.

Install door louver         G1 0.7           Install door hinges, 1 set         G0 0.8           Replace door stop (moulding), 17 1F         G3 0.9           Lubricate builders hardware         G9 0.6           Replace door handles/pulls         H6 0.7           Install door savers         I4 0.9           Replace door weatherstripping         I5 0.8		
Resecure/rehang wood door       F8 0.6         Cut off door bottom, 1 each       F8 0.6         Trim door to fit       F9 0.4         Install door louver       G1 0.7         Install door hinges, 1 set       G0 0.8         Replace door stop (moulding), 17 1F       G3 0.9         Lubricate builders hardware       G9 0.6         Replace door handles/pulls       H6 0.7         Install door savers       I4 0.9         Replace door weatherstripping       I5 0.8	27	0.0
Cut off door bottom, 1 each       F8       0.6         Trim door to fit       F9       0.4         Install door louver       G1       0.7         Install door hinges, 1 set       G0       0.8         Replace door stop (moulding), 17 1F       G3       0.9         Lubricate builders hardware       G9       0.6         Replace door handles/pulls       H6       0.7         Install door savers       I4       0.9         Replace door weatherstripping       15       0.8	30	0.0
Trim door to fit F9 0.4  Install door louver G1 0.7  Install door hinges, 1 set G0 0.8  Replace door stop (moulding), 17 1F G3 0.9  Lubricate builders hardware G9 0.6  Replace door handles/pulls H6 0.7  Install door savers I4 0.9  Replace door weatherstripping I5 0.8		
Install door louver G1 0.7 Install door hinges, 1 set G0 0.8 Replace door stop (moulding), 17 1F G3 0.9 Lubricate builders hardware G9 0.6 Replace door handles/pulls H6 0.7 Install door savers I4 0.9 Replace door weatherstripping I5 0.8	21	0.0
Replace door stop (moulding), 17 1F  Lubricate builders hardware  G9 0,6  Replace door handles/pulls  H6 0,7  Install door savers  I4 0.9  Replace door weatherstripping  I5 0.8		
Replace door stop (moulding), 17 1F  Lubricate builders hardware  G9 0,6  Replace door handles/pulls  H6 0,7  Install door savers  I4 0.9  Replace door weatherstripping  I5 0.8		
Lubricate builders hardwareG90,6Replace door handles/pullsH60.7Install door saversI40.9Replace door weatherstrippingI50.8		
Replace door handles/pullsH60.7Install door saversI40.9Replace door weatherstrippingI50.8		
Install door savers I4 0.9 Replace door weatherstripping I5 0.8		
• • • • • • • • • • • • • • • • • • • •		
Challen de anticipalement	A7	0.5
Caulking doors/windows J7 0.9	A6	0.5
Base rubber replacement, 4 ft	01	0.0
Align/adjust storm doors 18 0.7		
Install door bottom sweep I9 0.5		
Cut door bottom/raise threshold J1 1.3		
Replace glass in wood door J5 1.2	17	0.0
Replace glass in metal door J6 1.3	18	0.0
Replace glass in plate glass in door	16	0.0
Remount/replace window unit F7 1.0		
Repair door knob	23	0.0
Replace/install door knob	24	0.0
Repair/replace wooden door jamb	28	0.0
Repair/replace door/window jamb	29	0.0

#### APPENDIX B:

# HIGH FREQUENCY TASK LIST FOR FORTS BLISS, DEVENS, AND EUSTIS

Repair Door Knob

Replace/Install Door Knob

Aluminum Combination Clip/Locknut

Repair Cylinder Lockset

Cut Key From Sample (Single-Sided)

Replace Closet Door Hanger

Repair Interior Door and Hardware

Plane (To Fit) Door

Resecure/Rehang Wood Door

Repair/Replace/Realign/Adjust Sliding Door

Patch Hole in Sheet Rock, 1 sq ft

Replace 1 to 10 Pieces of Asphalt Floor Tile

Replace Suspended Ceiling Panel

Repair/Replace Towel Rack

Caulk Around Bathtub

Repair Flush Valve/Ballcock

Repair Faucet Leak

Repair Lavatory Faucets

Replace Seat Washer 'O' Ring

Unplug Tub

Replace Fire Alarm Battery

Relamp Incandescent Light Fixture

Relamp Fluorescent Fixture

Erase Window Free

#### APPENDIX C:

# HIGH COST TASK LIST FOR FORTS BLISS, DEVENS, AND EUSTIS

Repair Interior Door and Hardware

Repair Cylinder Lockset

Repair Door Knob

Repair/Replace Aluminum Combination Storm Door Handle

Replace up to 36 sq in. of Wood Sash

Resecure/Rehang Wood Door

Repair Door Jamb

Repair/Replace/Realign/Adjust Sliding Door

Replace 1 to 10 sq ft of Asphalt Floor Tile

Repair Plaster 10 to 20 sq ft

Caulk Around Bathtub

Repair Flushometer

Repair Flush Valve/Ballcock

Replace P-Trap

Replace Pipe Fitting

Repair Faucet Leak

Repair Lavatory Faucets

Unplug Bathtub

Replace Outlet Cover Plate

Relamp Incandescent Light Fixtures

#### USACERL DISTRIBUTION

US Military Academy 10996 Chief of Engineers ATTN: Survivability Sect. CCB-OPS ATTN: CEHEC-IM-LH (2) ATTN: Facilities Engineer ATTN: Dept of Geography & ATTN: Infrastructure Branch, LANDA ATTN: CEHEC-IM-LP (2) ATTN: CECC-P . Computer Sciences ATTN: MAEN-A HQ USEUCOM 09128 ATTN: CECW ATTN: ECJ 4/1-LOE ATTN: CECW-O ATTN: CECW-P AMC - Dir., Inst., & Svcs. ATTN: CECW-RR ATTN: DEH (23) Fort Belvoir, VA ATTN: CEMP ATTN: Australian Liaison Officer 22060 ATTN: Water Resource Center 22060 DLA ATTN: DLA-WI 22304 ATTN: CEMP-C ATTN: Engr Studies Center 22060 ATTN: CEMP-E ATTN: CERD DNA ATTN: NADS 20305 ATTN: Engr Topographic Lab 22060 AT'IN: ATZA-TE-SW 22060 ATTN: CERD-L ATTN: CECC-R 22060 ATIN: CERD-C FORSCOM (28) FORSCOM Engineer, ATTN: Spt Det. 15071 ATTN: CERD-M ATTN: DEH CECRL, ATTN: Library 03755 ATTN: CERM ATTN: DAEN-ZCE ATTN: DAEN-ZCI HSC CEWES, ATTN: Library 39180 ATTN: DAEN-ZCM Ft. Sam Houston AMC 78234 ATTN: HSLO-F HQ, XVIII Airborne Corps and ATTN: DAEN-ZCZ Ft. Bragg 28307 Fitzsimons AMC 80045 ATTN: AFZA-DEH-EE ATTN: HSHG-DEH CEHSC ATTN: CEHSC-ZC 22060 Walter Reed AMC 20307 AMMRC 02172 ATTN: DET III 79906 ATTN: Facilities Engineer ATTN: CEHSC-F 22060 ATTN: DRXMR-AF INSCOM - Ch, Instl. Div. ATTN: DRXMR-WE ATTN: CEHSC-TT-F 22060 ATTN: CEHSC-FE-B 22060 Arlington Hall Station 22212 Norton AFB, CA 92409 ATTN: Engr & Hsg Div US Army Europe Vint Hill Farms Station 22186 ATTN: AFRCE-MX/DE ODCS/Engineer 09403 ATTN: IAV-DEH ATTN: AEAEN-FE Tyndall AFB, FL 32403 Ft. Belvoir 22060 ATTN: Facilities Engineer (3) ATIN: AEAEN-ODCS AFESC/Engineering & Service Lab V Corps ATTN: DEH (11) NAVFAC USA AMCCOM 61299 VII Corps ATTN: AMSMC-RI ATTN: Division Offices (11) ATTN: DEH (16) ATTN: AMSMC-IS ATTN: Facilities Engr Cmd (9) ATTN: Naval Public Works Center (9) 21st Support Command ATTN: DEH (12) Military Dist of Washington ATTN: Naval Civil Engr Lab (3) USA Berlin ATTN: DEH ATTN: Naval Constr Battalion Ctr 93043 ATTN: DEH (9) Cameron Station (3) 22314 Fort Lesley J. McNair 20319 Allied Command Europe (ACE) Engineering Societies Library New York, NY 10017 ATTN: ACSGEB 09011 Fort Myer 22211 ATTN: SHIHB/Engineer 09055 Military Traffic Mgmt Command ATTN: AEUES 09168 National Guard Bureau 20310 USASETAF Falls Church 20315 Installation Division ATTN: AESE-EN-D 09019 Oakland Army Base 94626 Bayonne 07002 US Government Printing Office 20401 8th USA, Korca (19) Sunny Point MOT 28461 Receiving/Depository Section (2) ROK/US Combined Forces Command 96301 NARADCOM, ATTN: DRDNA-F 01760 US Army Env. Hygiene Agency ATTN: EUSA-HHC-CFC/Engr ATTN: HSHB-ME 21010 TARCOM, Fac, Div. 48090 Ft. Leonard Wood, MO 65473 Nat'l Institute of Standards & Tech 20899 ATTN: Canadian Liaison Officer TRADOC (19) ATTN: German Liaison Staff HQ, TRADOC, ATTN: ATEN-DEH 23651 Defense Technical Ino. Center 22304 ATTN: British Liaison Officer (2) ATTN: DTIC-FAB (2) ATTN: DEH ATTN: French Liaison Officer TSARCOM, ATTN: STSAS-F 63120 USA Japan (USARJ) 266 ATTN: DCSEN 96343 6/90 ATTN: Facilities Engineer 96343 Fort Huachuca 85613 ATTN, DEH-Okinawa 96331 ATTN: Facilities Engineer (3)

Fort Ritchie 21719

ATTN: DEH

ATTN: APEN-A

WESTCOM Fort Shafter 96858

Area Engineer, AEDC-Area Office Amold Air Force Station, TN 37389

416th Engineer Command 60623

ATTN: Facilities Engineer